

25th January 1933]

APPENDIX I.

[Vide answer to question No. 489 asked by Mr. M. Devadasan at the meeting of the Legislative Council held on the 25th January 1933, page 299 supra.]

Expenditure during 1931-32.

Item number and name of work.	Total charges during the year.	Ayacut, if below 200 acres.	
		RS.	ACS.
<i>I. 15A-2. Irrigation—Minor.</i>			
1 Constructing a dividing dam for Sengulam and Pudukulam in Mettukal channel	2 8 0		
<i>II. 15 A-2. Extension and Improvements.</i>			
1 Improvements to Manur anicut	9,166 0 0		
2 Do. channel	2,155 8 0		
3 Constructing a stop wall at the head of leading channel to Gangikondan tank	5,503 2 0		
4 Making up the bund and strengthening the same and stopping leakages in Venganaicken anicut	1,430 14 7		
5 Reconstructing sluice No. 1 in Pattapathu tank, Tenkasi taluk	170 3 6		137
6 Constructing an outlet across the spill course from Aintharuvayar river above Elanji anicut, Tenkasi taluk	3,992 0 0		
7 Forming and strengthening left and right flood banks of Ariyanayagipuram anicut	683 0 0		
<i>Part contribution.</i>			
8 Improvements to Kalasthi weir outlet No. 2 in Singampatti Perungal (extending body wall and revetting slope)	140 12 0		
9 Providing and fixing mile, furlong stones in the bank of Pappankulam channel	199 0 0		180
10 Providing low wing wall at left end of the anicut in rear and providing in continuation up to existing revetment across Puliur anicut	182 2 9		
11 Surveying and levelling operations in Tinnevely division for 1931-32	133 6 0		
12 Surveying and levelling operations for 15. A. 2. Irrigation works in Tinnevely division for 1932	43 12 6		
13 Providing mile, furlong, half-furlong stones in Vadukachmathil tank and supply channel	94 2 0		
<i>15 A-2. Extension and Improvements.</i>			
14 Providing and fixing mile, furlong and half-furlong stones to Nambireddi channel	253 4 0		
15 Providing mile and furlong stones to I. No. 50, Pannakudian channel	112 12 0		
16 Providing mile and furlong stones to Sengalakurichi tank and supply channel	171 4 0		
17 Providing mile and furlong stones to Valliyur tank and supply channel	387 5 0		
18 Providing mile and furlong stones to Padalayarkulam tank and channel	94 10 0		
19 Providing mile and furlong stones to Thirukarangudi tank	65 2 0		

[25th January 1933]

Item number and name of work.	Total charges during the year.			Ayacut if below 200 acres.
15 A-2. Irrigation, Maintenance and Repairs.				
	RS.	A.	P.	ACS.
1 Special repairs to Vasudevanallur-Periakulam ..	81	0	0	
2 Repairs to Pambli-Periakulam	688	13	6	
3 Special repairs to Shellianallur anicut	31	0	0	
4 Special repairs to Pillayarkulam anicut	118	0	0	
5 Special repairs to Nanguneri-Periyakulam tank ..	1,207	10	0	
6 Repairs to Ukkirakottai anicut, leading channel and head sluice	1,190	0	0	
7 Repairs to Manur channel	16,022	11	0	
8 Diversion of Pudukulam branch of Mettukal channel.	730	8	0	
9 Closing branches in Karivalam-Vandanallur tank ..	1,471	0	0	
10 Miscellaneous repairs to Korayar weir in Kanadian channel	649	3	0	
11 Making up the bund and repairing sunk revetment, Pattapathi tank	1,117	12	0	137
12 Making up bund, etc., Valliyur-Periakulam	1,060	0	0	
13 Making up bund and providing revetment in scoured places, Nainarkulam tank	1,338	0	0	
14 Making up the scoured bank and repatching damaged revetment of Erayadi channel above and below drop No. 1	1,221	8	0	
15 Raising the right bank in the first reach of Tinnevely channel	1,751	14	0	
16 Underpinning body wall of Sivalayangal anicut across Hanumanadhi	239	10	0	
17 Making up bund and repairing revetment Vadukachimathil tank and channel	2,245	8	0	
18 Strengthening bund extending and raising the front revetment Sakalaneri tank	2,442	8	0	
19 Repairs to Kothikal anicut across Mammutthar river.	399	15	0	
20 Underpinning body wall, etc., Puliur anicut across Chittar	691	7	5	
21 Removing silt and cleaning narrow reaches of North Kodamelalagian channel 6/5 to 9/2	380	0	0	
22 Emergent repairs to Manjapalli anicut	842	2	0	
23 Strengthening training wall and forming left bank of leading channel to Gangaikondan tank	2,608	0	0	
24 Repairs to Peikulam and Vannankulam tanks	400	15	6	
25 Raising low banks of Kangayam channel from Pudukulam weir to Peikulam inlet	1,837	8	0	
26 Maintenance scheme estimate of Kodagan channel for 1931	5,762	11	0	
27 Conservancy establishment required for maintenance of channels and tanks in Tinnevely division for 1931	4,595	14	0	
28 Repairs to Pambli anicut and channel for 1931	1,426	15	6	
29 Maintaining the Surandai anicut for 1931	4,442	12	0	
30 Maintaining the Pavoer anicut for 1931	678	8	0	
31 Maintaining the Thiruchittambalam anicut for 1931 ..	1,098	5	0	
32 Annual repairs to Kodamelalagian temporary anicut for 1931	645	3	0	
33 Annual repairs to Kanadian anicut for 1931	1,269	8	0	
34 Maintenance scheme estimate, Tinnevely channel, for 1931	5,619	15	0	
35 Maintenance scheme estimate, Palayam channel, for 1931	10,846	10	0	
36 Annual repairs to North Kodamelalagian channel for 1931	1,307	0	0	
37 Annual repairs to Nadhiyunni anicut for 1931	1,436	7	0	
38 Special repairs to Kakkanallur supply channel	1,088	11	0	
39 Special repairs to the Arasapathu channel	969	1	0	

25th January 1933]

Item number and name of work.	Total charges during the year.			Ayacut if below 200 acres.
15 A-2. Irrigation, Maintenance and Repairs—cont.				
	RS.	A.	P.	ACS.
40 Special repairs to Kangayan anicut	1,145	12	0	
41 Annual repairs to Palavur anicut for 1931	2,073	4	0	
42 Repairs to I. No. 28, Thenikulam tank under Kodagan channel	2,159	8	0	21
43 Annual repairs to the Ariyanayagipuram anicut across Tambraparni river	1,130	15	0	
44 Annual repairs to Suttamalli anicut across Tambraparni river	2,238	10	0	
45 Making up the bund, etc., Peruvarisuryan tank ..	914	4	5	100
46 Repairs to Andichimadagu weir in Nangunerian channel	979	15	7	
47 Annual maintenance of the Kanadian channel, tanks fed by the channel	16,229	5	0	
48 Repairs to Pannakudian anicut across Pachayar ..	767	13	0	
49 Clearing silt and removing rocky obstructions in Kodagan channel	3,572	0	0	
50 Repairs to outlets 1 to 4, Pannakudian channel ..	823	10	0	
51 Repairs to I. No. 208, Pudugraman tank, Kodagan channel	763	1	0	125
52 Repairs to I. No. 214, Pettai-Periakulam under Kodagan channel	37	7	0	
53 Urgent repairs to the masonry works of Ariraperi tank I. No. 260, Tenkasi	966	11	0	186
54 Repairs to Subbukutti anicut across Pachayar river.	1,921	11	0	
55 Repairs to Semmatti weir of Singampatti Perungal channel	948	4	0	
56 Ordinary repairs to Karumandiamman channel ..	6	0	0	
57 Conservancy establishment required for maintenance of tanks in Tinnevely subdivision	746	6	0	
58 Annual repairs to the Suttamalli anicut across Tambraparni	232	0	0	
59 Repairs to flood damages, Kanadian channel	974	1	0	
60 Annual repairs to Kanadian anicut for 1932	1	8	0	
61 Annual repairs to Kanadian channel	24	0	0	
62 Annual repairs to the Kangayan channel for 1932 ..	2	0	0	
63 Annual repairs to the temporary anicut, Papanasam.	305	7	2	
64 Conservancy establishment for maintenance of channels, etc., Shermadevi subdivision	908	13	0	
65 Revetting left bank of Arasapattu channel in Manjalodai limits	1,144	8	0	
66 Repairs to flood damages, Kuthalaperi channel ..	649	0	0	
67 Repairs to flood damages of 1931 in Surandai tank and channel	751	4	6	
68 Closing breaches Shellianallur supply channel and tank	1,396	10	0	
69 Repairs to flood damages of 1931, Tinnevely channel.	2,526	11	0	
70 Repairs to flood damages of 1931, Kodagan channel.	1,142	0	0	
71 Annual repairs to Ariyanayagipuram anicut for 1932.	255	8	0	
72 Repairs to flood damages of Palayam channel ..	979	9	0	
73 Repairs to Pillayarkulam anicut, channel, etc. ..	893	0	0	
74 Closing breaches in Gangaikondan leading channel ..	102	0	0	
75 Closing breaches in Piranjeri supply channel	357	0	0	
76 Repairs to flood damages, Kangayan channel and tanks	661	4	8	
77 Repairs to flood damages, Nadhiyunni anicut	7	3	0	
78 Rent on canal telephone lines	103	8	0	
79 Renewing the worn out screw gearing shutters of Suttamalli anicut across Tambraparni river	20	12	0	
80 Replacing rotten worn out shutters, etc., in Vadukachimathil tank	13	3	0	

[25th January 1933]

Item number and name of work.	Total charges during the year.			Ayacut if below 200 acres.
15 A-2. Irrigation, Maintenance and Repairs—cont.				
	RS.	A.	P.	ACS.
81 Repairs to Kilanatham-Pudukulam tank under Palayam channel	70	0	0	
82 Repairing damaged crest and building three buttress wall in the body-wall of Kulasekaraperi dam across Palayar river	140	9	0	
83 Making up the right bank above and below Eraiyadi channel dividing dam	77	0	0	
84 Making up bund and repairing sluice in Kulasekaraperi tank	255	13	6	30
85 Making up bund of Uranipathu tank in Tenkasi taluk	106	0	0	137
86 Repairs to Devanallur tank	484	0	0	
87 Strengthening left bank of Arasapathu channel in Manjanodai limits.	186	8	0	
88 Repairs to Sivan Pillai anicut and channel	685	10	0	57
89 Special repairs to the Pannakudian channel I. No. 59	416	0	0	
90 Tarring and oiling of shutters and screw gearings of tanks and channels in Tinnevely division for 1931.	208	3	9	
91 Maintenance of the inspection bungalow at Kalakad for 1931	108	0	0	
92 Maintaining the inspection bungalow at Thirukaragudi	121	3	0	
93 Annual repairs to inspection bungalow at Kannadian anicut for 1931	1	10	0	
94 Annual repairs to shutter shed in the Kannadian anicut for 1931	0	14	0	
95 Annual repairs to lascars' shed, Kannadian anicut for 1931	0	8	0	
96 Annual repairs to Idaiyathukal channel for 1931	56	1	0	18.5
97 Union and municipal taxes on buildings other than residential	8	4	0	
98 Clearing sand in the drainage of wet land under Pottaikulam tank in Thirumalaikolundupuram village	300	0	0	
99 Repairs to Vandankulam tank	317	8	0	65
100 Repairs to Kothikal channel	353	10	0	187
101 Repairs to Ambur-Perungal channel	719	2	0	
102 Annual repairs to South Kodamelalagian channel for 1931	711	9	0	
103 Special repairs to the anicut at the head of Gadamanadhi Thenkal	784	3	0	
104 Special repairs to Kakanallur anicut	606	6	0	
105 Special repairs to the lascars' shed, Thachanallur	83	0	0	
106 Repairs to Koravan weir of North Kodamelalagian channel	200	12	0	
107 Special repairs to Manjapalli channel	222	0	0	
108 Special repairs to outlet 1 to 4 in Gadamanadhi-Thenkal channel	618	12	0	
109 Special repairs to the Adachani anicut and channel.	555	15	0	
110 Annual repairs to Nathiyunni channel for 1931	819	11	0	
111 Providing shutters to sluice Nos. 1, 2, 3 and 5 and other repairs to sluices in Adachani-Periyakulam..	131	7	0	
112 Annual repairs to the Kodamelalagian anicut for 1931	349	15	0	
113 Ordinary repairs to Puduparayankulam I. No. 175	66	8	0	
114 Removing shoal and excavating leading channel in front of surplus escape Pambili, Periyakulam	143	0	0	
115 Special repairs to Adachani supply channel	112	12	0	
116 Repairs to No. 2 anicut across Pachayar at the head of Padmaneri tank and supply channel	438	11	9	

25th January 1933]

Item number and name of work.	Total charges during the year.			Ayacut if below 200 acres.
15 A-2. Irrigation, Maintenance and Repairs—cont.				
	RS.	A.	P.	ACS.
117 Revetting sides of the bund at breach site of Thirukarangudi tank	246	14	0	
118 Kuthalaperi supply channel, clearing vegetation ..	6	0	0	
119 Reconstructing the damaged skin wall in Pappankal.	1	9	6	
120 Special repairs to Ambur-Perungal anicut	688	3	0	
121 Repairs to I. No. 216. Mullikulam under Kodagan channel	572	1	0	34
122 Repairs to I. No. 215. Thamaraiikulam under Tinnevelly channel	485	3	0	119
123 Special repairs to Kandamangalam anicut across Aluthakanniar river	679	11	0	
124 Emergent repairs to sluices in Thirukarangudi, Periyakulam	98	14	0	
125 Repairs to Marankulam tank	382	7	0	143
126 Repairs to I. No. 224. Pirayankulam tank under Tinnevelly channel	260	0	0	47
127 Special repairs to lascar shed, Suttamalli anicut ..	74	0	0	
128 Closing breaches in Nettur channel	57	0	0	
129 Special repairs to inspection bungalow, Kannadian anicut	46	0	0	
130 Repairs to division dam, etc., in Pavur channel ..	256	12	0	
131 Emergent repairs to bund of Thidiyur Sengulam tank	755	13	0	
132 Urgent repairs to Pallathu sluice No. 158 of Aryarkulam under Palayam channel	403	0	0	170
133 Repairs to flood damages of 1931 of Melakallur Pudukulam	406	8	0	130
134 Special repairs to the lascar shed at the Kanadian anicut	74	0	0	
135 Special repairs to shutter shed at the Kanadian anicut	48	0	0	
136 Special repairs to Poonjadikulam tank in Ambasamudram taluk	182	0	0	
137 Emergent repairs to Mela Thachakulam	281	0	0	
138 Union tax for Public Works Department inspection bungalow at Kalakad for 1931	3	4	0	
138-A Union tax for Public Works Department shutter shed Andichimadagu, Kalakad for 1931 ..	1	0	0	
139 Union and municipal taxes on buildings other than residential buildings for 1932	7	0	0	
140 Special repairs to triple dam across Thenkal channel of Chittar	289	0	0	
141 Special repairs to lascar shed at Melapavur of Tenkasi taluk	123	0	0	
142 Ringbunding breach in the body-wall of Nathiyunni anicut	184	10	0	
143 Tarring and oiling shutters and screw gearing of sluices in Tinnevelly division for 1932	56	0	0	
144 Annual maintenance of Public Works Department inspection bungalow, Tirukarangudi for 1932 ..	40	3	0	
145 Annual maintenance of inspection bungalow at Kalakad for 1932	43	6	0	
146 Repairs to flood damages of 1931 in Thiruchittambalam channel in Tenkasi taluk	283	8	0	163
147 Repairs to flood damages of 1931 in Ambur Perungal channel I. No. 174	462	5	0	
148 Repairs to flood damages in Kakkanallur channel and its tanks Nedungulam and Poonjadikulam ..	231	4	0	
149 Providing shutters and locking arrangements for scouring vents in outlet No. 1 of Pannakudian channel I. No. 59	53	0	0	
150 Repairs to flood damages of 1931 in Idayathukal ..	548	8	0	18.5
151 Closing breaches in Nathiyunni channel I. No. 167 ..	52	0	0	

[25th January 1933]

Item number and name of work.	Total charges during the year.	Ayacut if below 200 acres.		
	RS.	A.	P.	ACS.
15 A-2. Irrigation, Maintenance and Repairs—cont.				
152 Repairs to flood damages of 1931 in Adachani anicut channel and Periyakulam	101	0	0	
153 Ordinary repairs to Kangayan anicut for 1932 ..	6	10	8	
154 Closing breaches in South Kodamelalagian channel..	75	0	0	
155 Closing breaches in Adachani anicut and channel ..	44	0	0	
156 Special repairs to the shutter shed Vannampacheri ..	62	0	0	
157 Closing breaches in Kila Chinthamani Periyakulam	510	8	0	
158 Special repairs to shutter shed at Rajavillipuram ..	69	0	0	
159 Repairs to flood damages of 1931 in Arasapathu channel	374	14	0	
160 Repairs to flood damages of 1931 in Nathiyunni channel	59	0	0	

Tank Restoration Scheme works.

1 Repairs to Pettaikulam tank, Alagiapandiapuram group	100	10	0	24
2 Repairs and improvements to VII-B of Perungal channel	237	7	0	
3 Repairs to Thuppakudi Periyakulam and supply channel, Devarkulam group	901	4	0	
4 Repairs to Anandankulam tank	138	0	0	
5 Planting R.S. beams to the temporary anicut across Tambraparni river at Papanasam	8	12	0	
6 Repairs to No. 2 Pappankulam tank of Madankulam group	195	8	0	
7 Repairs and improvements to No. 206 Pappankal channel	466	7	0	
8 Repairs and improvements to Vadakal and Thenkal.	0	12	0	
9 Repairs to Alkolli anicut and head sluice across Ramanadhi C.R. No. 1 and T.R.S. No. 28-29 ..	551	6	0	
10 Repairs to Somaithangikulam of Mannarkoil village D.R. No. 1/29-30	89	0	0	58
11 Repairs to Vadapathikulam supply channel, C.R. No. 4/29-30	917	8	0	
12 Repairs to No. 4 Kalkurichikulam of Devarkulam group in Pappankulam village D.R. No. 20/29-30.	67	4	0	
13 Repairs to isolated Pallakal Periyakulam and Pettai-kulam tank, C.R. No. 8 and T.R.S. No. 29-30 ..	1,217	14	0	184.17
14 Repairs to No. 3 Madankulam tank and supply channel D.R. No. 2/30-31	2,672	2	0	
15 Repairs to No. 1 Vadapathikulam tank and supply channel from Jambunadhi Vadapathikulam group.	1,632	0	0	
16 Repairs to Pallakulam of Pallankal group, D.R. No. 19/29-30	4	5	0	27
17 Repairs to No. 2 Thondamankal tank Valathukal group, D.R. No. 12/30-31	361	0	0	187
18 Repairs to No. 1 Valathakulam tank of Valathakulam group	744	0	0	138